## Abstract

## PROCESS TO EXTRACT PHENOLIC COMPOUNDS FROM A RESIDUAL PLANT MATERIAL USING A HYDROTHERMAL TREATMENT

5

15

20

The hydrothermal treatment is based on placing the crude residual plant material in contact with hot water in a closed reactor, comprising the following steps:

- a) placing the material to be treated in contact with water in a closed reactor, and adjusting the solid/liquid ratio so that it ranges from 1/5 to 1/15 (w/v):
  - b) stirring;
  - c) heating to a temperature between 180 and 240°C, and at a pressure so that the water is maintained in liquid phase;
  - d) constantly stirring the mixture for a time period between 4 and 30 minutes; and
  - e) cooling the reactor to approximately 40°C, unloading the mixture, filtering and recovering the liquid fraction.

Figure 1.